

Technical Support and E-Warranty Certificate www.vevor.com/support

4-JAW SELF-CENTERING WOOD CHUCK

MODEL: KP2-3/4, KP96, KP965

We continue to be committed to provide you tools with competitive price.

"Save Half", "Half Price" or any other similar expressions used by us only represents an estimate of savings you might benefit from buying certain tools with us compared to the major top brands and doses not necessarily mean to cover all categories of tools offered by us. You are kindly reminded to verify carefully when you are placing an order with us if you are actually saving half in comparison with the top major brands.




4-JAW SELF-CENTERING WOOD CHUCK

MODEL: KP2-3/4, KP96, KP965







NEED HELP? CONTACT US!

Have product questions? Need technical support? Please feel free to contact us:

CustomerService@vevor.com

This is the original instruction, please read all manual instructions carefully before operating. VEVOR reserves a clear interpretation of our user manual. The appearance of the product shall be subject to the product you received. Please forgive us that we won't inform you again if there are any technology or software updates on our product.

Geometry accuracy (mm)

Diagram of test	Test item	Chuck Diameter	
		70	96
p p	a.Radial run-out	a:0.005 b:0.005	
	b.axial run-out		
	Radial run-out of chuck	≤0.15	≤0.15
	Axial run-out of chuck	≤0.15	≤0.15
	Radial run-out of test bar	α≤0.4 L=50	α≤0.4 L=50 (75)


DESCRIPTION

This Chuck is 4-Jaw Self-Centering chuck utilizing the precision, simplicity and reliability of the engineering chuck.

This Chuck is self-centering; grips internally and externally; will hold round and square work; has a hollow center so through boring can be done from either end; and can be run clockwise or anticlockwise.

Manufactured from, this gives the chucks a higher durability ensuring a longer life and high quality finish which is less.


PACKING LIST



(KP965)

1.4-Jaw Self-Centering Chuck1pcs	
2.Accessory	
Wooden Screw1pcs	;
T-bar Allen Key 1pcs	3
Key chuck 1pcs	;
Adapter1pcs	3
Big Round Jaw (4 pieces) 1set	S
Pin Jaw (4 pieces) 1se	ts
Step Jaw (4 pieces)1se	ts
Flat Jaw (4 pieces)1set	ts

Stud......16pcs



3. Instruction

SAFETY PRECAUTIONS

- 1. Read and und 9 and instructions anual before operation wood lathe.
- 2.. Always wear eye protection.
- 3. Do not wear gloves, neckties, jewelry or loose clothing.
- 4. Do not operate without guards in place.
- 5. Rough out workpiece before installing face plate.
- 6. Do not mount a split workpiece or one containing a knot.
- 7. Tighten all locks before operating.
- 8. Rotate workpiece by hand before applying power.
- 9. Use slowest speed when starting a new workpiece and do not exceed


permitted speed.

- 10.Disconnect machine from power source before making repairs or adjustments.
- 11.Do not operate while under influence of drugs, alcohol or medication.
- 12. Remove the tool rest before sanding or polishing.

It is beyond the scope of this manual to describe all of the turning techniques that are possible with the 4-Jaw Chuck. It is recommended that beginner turners attend a reputable course of instruction refer to one of the many available books on turning techniques.


MOUNTING ON THE LATHE

The 4-Jaw Chuck fits a wide range of lathe spindle sizes. This is done by changing the threaded Adapter. Your dealer will adviseon the Adapter required for your lathe. Check that the Adapter is firmly screwed into the Chuck body and then screw the assembled chuck onto the lathe spindle. Adapter must be firmly seated against the lathe spindle shoulder.



THE SCREW POINT

The Screw Chuck is used to mount small, cross-grained pieces.



4-Jaw Self-Centering Chuck

25MM JAWS

These jaws are used for expansion into small recesses and for firm holding of fine spindle work, such as earrings, chess pieces, etc.. To turn very small articles, the jaws can be unscrewed and the backing jaws only can be used.

DOVETAIL JAWS

Dovetail jaws are designed for mounting bowls by expanding into a recess or clamping onto a spigot. The size indicated is the outside measurement of the jaw face when fully closed. Dovetail jaws provide approximately 25mm of expansion beyond their specified size.


KEY CHUCK

The 4-Jaw Chucks provide one-hand tightening along with tremendous griping power provided by the 6 to 1 ratio of the scroll. The totally enclosed back assures consistent, smooth action by preventing dust and debris from getting into scroll of the Chuck.

Key chuck cannot be beaten when it comes to holding power.

Its compact size makes it ideal for use on 300mm capacity lathes or smaller.

Basic Chuck includes: Chuck body, dovetail jaw set; T-Bar Allen Key;screw point; Key chuck; appropriate Adapter to fit your lathe and owner's manual.




1. T-bar Allen key	2.Screw	3.Lid	4.Screwdriver	
5.Adapter	6.Circlip	7.Scroll ring	8. Key chuck	
9.Pinion	10.Pin	11.Baking pin	12.Chuck body	
13.Backing jaw	14.jaws	15. Countersunk screw		
16. T-bar Allen key	17. Wood screw			

CLAMP-MODE

With this application the workpiece is held by the jaws. To achieve a good hold, press the bowl end hard against the jaws. Fasten the workpiece to the screw or onto a face plate. When pre-turning bowls from green timber it is possible to do this between centers or with a pivot chuck. Turn a 5 to 10mm deep dovetail recess first.

EXPANSION MODE

For this application arecess is turned into thework piece. The depth of the recess depends on the actual size of the workpiece as well as the type of timber used. The minimum depth should be 5mm to 10mm.



MAINTENANCE

The chuck is engineered to close tolerances and may initially be stiff to operate. With use movement will be easier. To maintain easy jaw action, regularly spray oil into the scroll and work Key chuck through full range of movement. Inspect chuck regularly for build-up of dust in the scroll and jaws. Clean as required.


BEGINNER'S HINTS

Prepare the wokpiece the following way:

200-250mm dia.40-50mm thick; RPM80- 100

- 1.Drill a 25mm deep and 7-8mm dia. hole in the center of workpiece (avoid drilling the end grain, less grip).
- 2. Make sure the work piece is as round as possible.

- 3. Choose appropriate speed before you start the lathe.
- 4. Screw the work piece hard against the jaws.
- 5.Heavy or unbalanced work pieces should not be fastened directly to the screw chuck. Use the faceplate rings instead.





Address: Baoshanqu Shuangchenglu 803long 11hao 1602A-1609shi

Shanghai

Imported to AUS: SIHAO PTY LTD, 1 ROKEVA STREETEASTWOOD

NSW 2122 Australia

Imported to USA: Sanven Technology Ltd., Suite 250, 9166 Anaheim

Place, Rancho Cucamonga, CA 91730



Pooledas Group Ltd Unit 5 Albert Edward House, The Pavilions Preston, United Kingdom



SHUNSHUN GmbH Römeräcker 9 Z2021, 76351 Linkenheim-Hochstetten, Germany

Made In China



Technical Support and E-Warranty Certificate www.vevor.com/support