

Technical Support and E-Warranty Certificate https://www.vevor.com/support

DESK CONVERTER USER MANUAL


We continue to be committed to provide you tools with competitive price.

"Save Half", "Half Price" or any other similar expressions used by us only represents an estimate of savings you might benefit from buying certain tools with us compared to the major top brands and doses not necessarily mean to cover all categories of tools offered by us. You are kindly reminded to verify carefully when you are placing an order with us if you are actually saving half in comparison with the top major brands.



Desk Converter

MODEL NO.: ZWE-ZSZ-01、ZWE-ZSZ-03



NEED HELP? CONTACT US!

Have product questions? Need technical support? Please feel free to contact us:

◯ CustomerService@vevor.com

This is the original instruction, please read all manual instructions carefully before operating. VEVOR reserves a clear interpretation of our user manual. The appearance of the product shall be subject to the product you received. Please forgive us that we won't inform you again if there are any technology or software updates on our product.

⚠ WARNING:

Please read this manual carefully before using the product. Failure to do so may result in serious injury. SAVE THIS MANUAL

Check carefully to make sure there are no missing or defective parts, mproper installation macause damage or serious injury. Do not use this product for any purpose that is not explicitly specified in this manual and do not exceed weight capacity. We cannot be liable for damage orinjury caused by improper mounting, incorrect assembly, or inappropriate use.



PINCH POINT

DO NOT place hands on or near support bars. Moving parts can crush and cut. Pinch points are created during lifting and lowering the worksurface Failure to follow these instructions may result inserious personal injury.


ASSEMBLY PRECAUTIONS

- 1. Assemble only according to these instructions. Improper assembly can create hazards.
- 2. Wear ANSI-approved safety goggles and heavy-duty work gloves during assembly.
- 3. Keep assembly area clean and well-lit.
- 4. Keep bystanders out of the area during assembly.
- 5.Do not assemble when tired or when under the influence of alcohol, drugs or medication.
- 6. The product capabilities apply to properly and completely assembled products only.
- 7. Assemble on a flat, level, hard and smooth surface capable of safely supporting the acrylic table.

USE PRECAUTIONS

TO PREVENT SERIOUS INJURY AND DEATH FROM TIPPING:

- 1. This product is not a toy. Do not allow children to play with or approach this item.
- 2. Use as intended only. Do not sit or stand on the table.
- 3. Inspect before every use. Do not use it if parts are loose or damaged.
- 4. Use only on flat, level, and hard surfaces.



≤44lbs (≤20KG)

CAUTION: DO NOT EXCEEDMAXIMUM LISTED WEIGHT CAPACITY. SERIOUS INJURY OR PROPERTY DAMAGE MAY OCCUR! 警告:不要超过列出的最大重量容量。可能发生严重伤害或财产损失!


ASSEMBLY INSTRUCTIONS

For additional information regarding the parts listed in the following pages, refer to the Assembly Diagram of this manual. Unwrap and separate all parts on a clear work area.


TECHNICAL SPECIFICATIONS


Model	ZWE-ZSZ-01	ZWE-ZSZ-03
Main Material	Steel + Board	Steel + Board
Color	Black	Black
Product Dimensions (LxWxH)	800*635*505 mm	915*756*505 mm
Packing Size (LxWxH)	875*500*155 mm	980*700*160 mm
Net Weight (kg)	10.85	13.75
Gross Weight (kg)	11.80	14.9

PACKAGE CONTENTS




ASSEMBLY STEPS





COMPLETION



Address: Baoshanqu Shuangchenglu 803long 11hao 1602A-1609shi Shanghai

Imported to AUS: SIHAO PTY LTD, 1 ROKEVA STREETEASTWOOD NSW 2122 Australia

Imported to USA: VEVOR STORE INC, 9448 RINCHMOND PL #E RANCHO CUCAMONGA, California, 91730 United States of America

EC REP

SHUNSHUN GmbH Römeräcker 9 Z2021,76351 Linkenheim-Hochstetten,Germany

UK REP

Pooledas Group Ltd Unit 5 Albert Edward House, The Pavilions Preston, United Kingdom



Support and E-Warranty Certificate https://www.vevor.com/support